Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

ED647 AVE V PUMP STATION. NY Spills S102146418
North AVE V PUMP STATION N/A

1/2-1 BROOKLYN, NY

0.955 mi.

5045 ft. Site 4 of 8 in cluster ED

 Relative:
 SPILLS:

 Higher
 Name:
 AVE V PUMP STATION.

 Actual:
 Address:
 AVE V PUMP STATION

 13 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 9301183 / 1995-02-15

 Facility ID:
 9301183

 Facility Type:
 ER

 DER Facility ID:
 91052

 Site ID:
 102869

DEC Region: 2 Spill Cause: Unknown Spill Class: C3 2401 SWIS: Spill Date: 1993-04-25 Investigator: **SMMARTIN** Referred To: Not reported Reported to Dept: 1993-04-25 CID: Not reported Water Affected: C.I. CREEK. Spill Source: Unknown Spill Notifier: Local Agency Cleanup Ceased: 1995-02-15 Cleanup Meets Std: True

Last Inspection:

Recommended Penalty:

UST Trust:

Remediation Phase:

True

Not reported

False

False

0

Date Entered In Computer: 1993-07-20
Spill Record Last Update: 1995-02-15
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

ADELUGBA/MARTIN "

Remarks: "HEAVY INFLUENT FLOW."

All Materials:

Site ID: 102869 Operable Unit ID: 983095 Operable Unit: 01 Material ID: 401907 Material Code: 0062A Material Name: raw sewage Case No .: Not reported Material FA: Other Quantity: .00

Units: Not reported

Recovered: .00

Oxygenate: Not reported